

February 29, 2024

Dear Valued Customer,

CANON ANELVA CORPORATION
 Component Development Div.
 Quality Management Div.

Cold Head Driver (P-021CD/P-022CD) End of Production

Thank you for choosing CANON ANELVA products.

We would like to inform you a discontinuation of the Cold head driver (P-021CD/P-022CD), which are embedded in CANON ANELVA equipment.

CANON ANLEVA promises to continuously improve the product quality and reliability, in order for ensuring all customers' satisfaction. Thank you for all of your support.

Sincerely,

NOTE

Discontinued and Substitute Parts

No.	Discontinued Parts		Substitute Parts
	Name	Part No.	Model
1	COLD HEAD DRIVER,021 ROHS	9009-11747	P-023CD-R
2	COLD HEAD DRIVER,022 ROHS	9009-11755	
3	Single operating unit	H21-03541	
4	SDU,UL	9005-48065	

Service Termination Date : March 28, 2031

We will continue to respond to maintenance, but due to the availability of replacement parts, Please note that we may not be able to repair it.

Please contact your nearest Sales or Service Office for more details.