Dear Valued Customer,

CANON ANELVA CORPORATION Quality Management Div.

Substitute Parts Notice for Fiber sensor amplifier by Panasonic

Thank you for using CANON ANELVA products.

We inform you the Substitute Parts of Fiber sensor amplifier by Panasonic equipped to our tools. We will continually improve the product quality and reliability to ensure customer satisfaction.

NOTE

Discontinued part and its substitute part

No.	Discontinued Parts (Panasonic)		Substitute Parts (OPTEX)	
	Model	Part No.	Model	Part No.
1	FX2-A3R-LEDB	N07225300 H11-27825	MDF-HTN	N07244497
Usage	electric discharge detection			

*The appearance, shape, and dimensions of the substitute part are different. Switching to substitute parts will require design changes including surrounding components.

Please contact your nearest Sales or Service Office for more details.